



REV Recreation Group
P.O. Box 1007
Decatur, IN 46733
(800) 322-8216

IMPORTANT RECALL INFORMATION #191126REV

January 2020

**TO: ALL REV RECREATION GROUP DEALER PRINCIPALS,
SERVICE MANAGERS AND PARTS MANAGERS**

**SUBJECT: RECALL CAMPAIGN #191126REV
Diesel Slideout Wiring and Plumbing**

REV Recreation Group, Inc., on behalf of its manufacturing center located in Decatur, Indiana, is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the United States National Traffic and Motor Vehicle Safety Act and the Canada Motor Vehicle Safety Act.

REV Recreation Group, Inc. has decided that a safety defect relating to motor vehicle safety exists in certain model year 2020 Fleetwood and Holiday Rambler brand Class A diesel motorhomes:

| <u>Product</u> | <u>Manufacturing date range</u> |
|---------------------------|-------------------------------------|
| Discovery | April 10, 2019 - September 23, 2019 |
| Discovery LXE | April 10, 2019 - September 30, 2019 |
| Pace Arrow LXE | May 14, 2019 - September 24, 2019 |
| Holiday Rambler Navigator | May 21, 2019 - September 17, 2019 |
| Holiday Rambler Endeavor | May 7, 2019 - September 6, 2019 |

We are notifying the owners of the affected units in order to correct the problem. Copies of the letters sent to owners of record are attached for your information.

WHAT IS THE PROBLEM?

On motorhomes affected by this recall, a wire harness/plumbing bundle installed in an articulating (moveable) slideout raceway, may have been improperly wrapped and secured within the slideout raceway. Without the proper securement method, the wire harness/plumbing bundle may become tangled and/or damaged by the metal slideout raceway that extends and retracts with the slideout room.

If the wire harness/plumbing bundle becomes damaged, a fire may result, posing the risk of personal injury or death.

WHAT SHOULD YOU DO?

Owners of the above mentioned motorhomes have been asked to contact an authorized REV Recreation Group dealer to have the described defect remedied. In the event that you are contacted by a customer, please verify eligibility by referring to the serial number range listed in the attached **Recall Service Bulletin #191126REV** prior to beginning repairs.

Once repairs have been completed according to **Recall Service Bulletin #191126REV**, have the customer sign your dealership's **Internal Repair Order**. Warranty labor claims are to be submitted electronically to REV Recreation Group. Customers will not be charged for these repairs.

If you have one of these vehicles in your inventory, you will be mailed a Safety Recall Notice for that specific motorhome. REV Recreation Group dealers are required to make repairs to stock units on dealer lots prior to sale or lease.



Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act) of 1966 requires that: If you have received a notice of recall or failure to comply from REV Recreation Group, Inc. or any component manufacturer, you must repair or otherwise correct the defect on vehicles remaining in your inventory according to the notification before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

Please carefully review this entire package with your parts and service staff to familiarize them with the step-by-step procedure and implement the Voluntary Recall Campaign.

Thank you for helping REV Recreation Group with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact your REV Recreation Group Service Center.

Sincerely,

REV RECREATION GROUP, INC.

Attachments: Recall #191126REV US Customer Letter
Recall #191126REV Canadian Customer Letters
Recall #191126REV Service Bulletin