## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

19V-869

Manufacturer Name: Daimler Trucks North America LLC NHTSA Recall No. / MFR Recall No.: 19V-869 /FL-841 Recall Subject: Fan Hub Bolts Improperly Torqued Owner Notification Beginning Date: JAN 16, 2020

**Owner Notification End Date: JAN 16, 2020** 



Repo	ort#	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	l	APR 28, 2020	2020-1	145	98	0	0

This Document Last Updated: APR 29, 2020

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.