

**Recall Quarterly Report****19V-869****Manufacturer Name :** Daimler Trucks North America LLC**NHTSA Recall No. / MFR Recall No. :** 19V-869 /FL-841**Recall Subject :** Fan Hub Bolts Improperly Torqued**Owner Notification Beginning Date :** JAN 16, 2020**Owner Notification End Date:** JAN 16, 2020

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JUL 29, 2020	2020-2	145	125	0	0
1	APR 28, 2020	2020-1	145	98	0	0

This Document Last Updated : JUL 29, 2020

**Definitions :**Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.