OMB Control No.: 2127-0004

Recall Quarterly Report

19V-869

Manufacturer Name: Daimler Trucks North America LLC NHTSA Recall No. / MFR Recall No.: 19V-869 /FL-841 Recall Subject: Fan Hub Bolts Improperly Torqued Owner Notification Beginning Date: JAN 16, 2020

Owner Notification End Date: JAN 16, 2020



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 3 | OCT 23, 2020 | 2020-3 | 145 | 138 | 0 | 0 |
| 2 | JUL 29, 2020 | 2020-2 | 145 | 125 | 0 | 0 |
| 1 | APR 28, 2020 | 2020-1 | 145 | 98 | 0 | 0 |

This Document Last Updated: OCT 28, 2020

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.