

Part 573 Safety Recall Report

19V-872

Manufacturer Name : Keystone RV Company

Submission Date : DEC 10, 2019

NHTSA Recall No. : 19V-872

Manufacturer Recall No. : 20-366



Manufacturer Information :

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 201

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2020-2020 Keystone Springdale 1700FQ, 1750RD, 1760BH, 1790FQ, 1800BH

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Units with Baja package that have incorrect tire rim size and axle on the Federal Identification Tag.

Production Dates : AUG 15, 2019 - SEP 04, 2019

VIN Range 1 : Begin : 4YDT18014LW103096 **End :** 4YDT18013LW103297 Not sequential

Description of Defect :

Description of the Defect : It has been decided that the vehicles in the recall population fail to conform to the requirements of Part 567, "Certification." The vehicles subject to this recall may have been manufactured with the incorrect information on the Federal Identification Tag. The tag indicates the rim size is 15x6, tire size is ST205/75R14D @ 75 psi. The correct rim size is 15x6, tire size is LT235/75R15D @ 65 psi. This does not affect the GVWR just wheel data.

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : Fails to conform to the requirements of Part 567, "Certification." An incorrect label may lead to unintentionally overinflating the tires, increasing the risk of a crash.

Description of the Cause : The incorrect rim, tire size, and psi were printed on the label.

Identification of Any Warning that can Occur : Rim, tire and psi on the Federal Identification Tag does not match information for the rim and tire.

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

11/26/2019 – Information was received through a routine audit that the Federal Identification Tag had incorrect sizes on it compared to what was on the camper.

11/27/2019 – Information was reviewed and investigation opened to determine range and scope.

12/6/2019 – Investigation concluded and scope completed. Determined the Federal Identification Tag would need to be replaced.

Description of Remedy :

Description of Remedy Program : The remedy is to replace the Federal Identification Tag.

How Remedy Component Differs from Recalled Component : The repair will conform to requirements of Part 567, "Certification."

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : JAN 15, 2020 - JAN 15, 2020

Planned Owner Notification Date : JAN 15, 2020 - JAN 15, 2020

* NR - Not Reported