

T-19-02

Dear Slingshot Owner,

Our records indicate that you are the owner of a Slingshot affected by Safety Recall **T-19-02** that was announced on December 12, 2019.

Polaris Slingshot has identified some 2019 vehicles built from 2/12/2019 through 7/31/2019 may have 10A circuit breakers that do not meet quality standards. Affected circuit breakers do not meet functional specifications and may cause an engine to unexpectedly stop running, increasing the risk of a crash. A letter will arrive at your address by postal mail that provides more information about the update and what you should do next.

Visit our [On-Road Safety Recall](#) page to verify if your Slingshot is impacted by the recall. Contact your dealer to schedule a service appointment or complete a transfer of ownership if you no longer own the vehicle. Your local POLARIS dealer can be found on our [Dealer Locator](#) page.

While your dealer is in the best position to answer your questions, you can also call our Polaris Owner Connections Department at **1-855-863-2284** to speak with a representative.

Sincerely,

Polaris On-Road Vehicles