



IMPORTANT SAFETY RECALL

July 2020

This notice applies to your vehicle, VIN: _____

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain tri-fold tonneau covers sold as accessories for 2019 – 2020 model year Chevrolet Silverado and GMC Sierra 1500 series trucks. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

<p>IMPORTANT</p> <ul style="list-style-type: none"> • Your vehicle is involved in GM safety recall N192285070. • Schedule an appointment with your GM dealer. • This service will be performed for you at no charge. You should schedule a service appointment with your GM dealer even if you believe that your vehicle has already received service for this condition. GM has updated the remedy procedure for the tri-fold tonneau covers previously subject to equipment recall 19E031 (N192217500).
--

Why is your vehicle being recalled?

Our records indicate that your vehicle may have the recalled tri-fold tonneau cover. The attachment system used on the tonneau cover may not properly secure the cover to the pickup bed. The cover may become loose and possibly detach from the pickup bed while driving. If the tonneau cover becomes loose, you may notice noise coming from the cover, damage to cover attachments, or cover movement against the truck's bed rails. A tonneau cover that separates or detaches from the pickup bed while driving, can become a road hazard, increasing the risk of a crash.

What will we do?

Your GM dealer will replace the tonneau rails and clamps and add a tether to prevent the tonneau from detaching onto the roadway. If the vehicle was covered by equipment recall 19E031, the dealer will also confirm that the repair for equipment recall 19E031 was correctly performed. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual inspection and service correction time of approximately 2 hours.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

Did you already pay for this repair?

Even though you may have previously had repairs for this condition, you will still need to take your vehicle to your dealer for additional repairs. If you have already paid for repairs for the recall condition, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170. The completed form and required documents must be presented to your dealer or received by the Reimbursement Department by July 31, 2021, unless state law specifies a longer reimbursement period.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-630-2438	1-800-833-2438
GMC	1-866-996-9463	1-800-462-8583
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 20E024.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Maryann L. Combs
Vice President
Global Vehicle Safety

Enclosure
GM Recall: N202305070