Part 573 Safety Recall Report

Manufacturer Name :Nova BusSubmission Date :JUN 11, 2020NHTSA Recall No. :20E-036Manufacturer Recall No. :CR4913

Manufacturer Information :

Manufacturer Name :	Nova Bus	Number of potentially involved :	2
Address :	1000 Industriel Blvd	Estimated percentage with defect :	100 %
	Saint-Eustache Quebec, Canada 00 JR7 5A5		
Company phone :	0110		

Population :

Equipment Information :

Model : Part No. : Size : Function :	10300949 NR
Production Dates :	OCT 01, 2018 - APR 01, 2020



20E-036

The information contained in this report was submitted pursuant to 49 CFR $\S573$

20E-036

Description of Defect :

Description of the Defect :	According to Agility Fuel Solution communication received: "The EMER- supplied thermally activated pressure relief devices (PRDs) listed above and installed on the subject CNG fuel systems may not vent the system when exposed to heat. This condition was identified during bench testing. Agility is not aware of any accidents, injuries, fires or other incidents related to this condition."
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	According to Agility Fuel Solution communication received: "If a PRD does not release, or is slow to release, during a fire on a fuel system, one or more system components may rupture, potentially causing equipment damage and/or personal injury."
Description of the Cause :	According to Agility Fuel Solution communication received: "The root cause is still being investigated."
Identification of Any Warning that can Occur :	According to Agility Fuel Solution communication received: "NR"

Involved Components :

Component Name :	Valve
Component Description :	Valve containing Emer PRD 2012T used in CNG fuel Systems
Component Part Number :	Mark 147-007

Supplier Identification :

Component Manufacturer

Name :	EMER S.p.A
Address :	via Bormioli 19
	Brescia FOREIGN STATES 25135 FOREIGN STATES
Country :	Italy

Chronology:

2020-05-13 Prevost Parts receives an email communication from Agility Fuel Solutions regarding the equipment recall 20E-019.

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

20E-036

Page 3

2020-05-26 Nova Bus contacts Agility to clarify the information communicated about the different configurations and date codes affecting Nova Bus configurations.

2020-05-26 Nova Bus informs NHTSA Recall Management Division that we are reviewing the information received with Agitlity to confirm the affected configurations at Nova Bus.

2020-06-03 Agility and Nova Bus confirm the affected configurations.

2020-06-10 Nova Bus confirms the affected market based on the affected configurations.

2020-06-11 Nova Bus informs NHTSA that a voluntary equipment recall will be released to address the safety-related defect.

Description of Remedy :

Description of Remedy Program :	According to Agility Fuel Solution communication received: "Agility intends to work with its OEM customers and distributors to arrange owner notifications and replacement of the potentially defective PRDs on affected vehicles. All of the subject products remain under the manufacturer's warranty. Therefore, pursuant to 49 CFR 577.11(e), Agility requests an exemption from the reimbursement plan requirements"
	According to Agility Fuel Solution communication received: "The defective PRDs will be replaced with PRDs that meet specifications."
	According to Agility Fuel Solution communication received: "Agility ceased using the subject PRDs in production as of April 1, 2020."

Recall Schedule :

Description of Recall Schedule :	Owner notification will be sent within 60 days of this notification. An advance copy of the owner letter will be provided to Transport Canada
	for review and approval prior to release.
Planned Dealer Notification Date :	JUL 17, 2020 - JUL 17, 2020
Planned Owner Notification Date :	JUL 17, 2020 ⁻ JUL 17, 2020

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Name : NR Address : NR NR Country : NR Company Phone : NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573