

Recall Quarterly Report**20E-056**

Manufacturer Name : Tong Yang Industry Co.
NHTSA Recall No. / MFR Recall No. : 20E-056 /
Recall Subject : Grille Moulding May Affect Cruise Control
Owner Notification Beginning Date : SEP 15, 2020
Owner Notification End Date: SEP 15, 2020



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 5 | OCT 30, 2021 | 2021-3 | 105 | 81 | 13 | 11 |
| 4 | JUL 28, 2021 | 2021-2 | 105 | 81 | 13 | 11 |
| 3 | APR 27, 2021 | 2021-1 | 105 | 81 | 13 | 11 |
| 2 | JAN 29, 2021 | 2020-4 | 105 | 81 | 13 | 11 |
| 1 | OCT 30, 2020 | 2020-3 | 105 | 82 | 12 | 11 |

This Document Last Updated : NOV 01, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.