

Part 573 Safety Recall Report

20E-058

Manufacturer Name : Firefly Integrations, LLC

Submission Date : SEP 23, 2020

NHTSA Recall No. : 20E-058

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Firefly Integrations, LLC

Address : 1013 Elroy Drive

Middlebury IN 46540

Company phone : (574) 825-4600

Population :

Number of potentially involved : 2,487

Estimated percentage with defect : 100 %

Equipment Information :

Brand / Trade 1 : Multiplex

Model : G9

Part No. : To Be Determined

Size : NR

Function : NR

Descriptive Information : Recall population to include all and only RV units which use a G9 electronic control module.

Production Dates : OCT 01, 2017 - AUG 20, 2020

Description of Defect :

Description of the Defect : G9 unit can fail if excessive voltage is applied.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Potential thermal event.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name : G9

Component Description : Control circuit Board

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR
Address : NR
NR
Country : NR
Company Phone : NR

* NR - Not Reported