OMB Control No.: 2127-0004

## Part 573 Safety Recall Report

### 20E-059

**Manufacturer Name:** Spyder Controls, Corp

**Submission Date :** AUG 21, 2020 **NHTSA Recall No. :** 20E-059

NHTSA

NATIONAL HIGHWAY TRAFFIC
SAFETY ADMINISTRATION

#### **Manufacturer Information:**

**Manufacturer Recall No.:** NR

Manufacturer Name: Spyder Controls, Corp

Address: 7102 - 52 St #10

Lacombe 00 T4L 1Y9

Company phone: 919-9092

#### **Population:**

Number of potentially involved : NR Estimated percentage with defect : NR

#### **Equipment Information:**

Brand / Trade 1: Spyder Controls, Corp

Model: G9

Part No.: To Be Determined

Size: NR Function: NR

Descriptive Information: Recall population to include all and only RV units which use a G9 electronic

control module.

Production Dates: OCT 01, 2017 - AUG 20, 2020

#### **Description of Defect:**

Description of the Defect: G9 unit can fail if excessive voltage is applied.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Potential thermal event.

Description of the Cause : NR
Identification of Any Warning NR
that can Occur :

#### **Involved Components:**

Component Name: NR
Component Description: NR
Component Part Number: NR

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: NR Address: NR NR

Country: NR

#### **Chronology:**

NR

#### **Description of Remedy:**

Description of Remedy Program: NR
How Remedy Component Differs NR
from Recalled Component:

Identify How/When Recall Condition NR
was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

#### **Purchaser Information:**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

# **Part 573 Safety Recall Report**

**20E-059** 

Page 3

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573