

Part 573 Safety Recall Report

20E-085

Manufacturer Name : Denso International America, Inc.**Submission Date :** SEP 30, 2021**NHTSA Recall No. :** 20E-085**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :****Manufacturer Name :** Denso International America, Inc.**Number of potentially involved :** 2,361,141**Address :** 24777 DENSO Drive
Southfield MI 48033**Estimated percentage with defect :** NR**Company phone :** 999**Equipment Information :****Brand / Trade 1 :** DENSO**Model :** Fuel Pump**Part No. :** Various Part Numbers**Size :** N/A**Function :** Fuel Supply**Descriptive Information :** The low-pressure fuel pump is located in the fuel tank and supplies fuel pressure to the fuel injection system.**Production Dates :** JUN 26, 2017 - SEP 24, 2019**Description of Defect :****Description of the Defect :** For Description of Defect, please see DIR filed April 24, 2020 attached to recall 20E-026.**FMVSS 1 :** NR**FMVSS 2 :** NR**Description of the Safety Risk :** For Description of Safety Risk please see DIR filed April 24, 2020 attached to recall 20E-026.**Description of the Cause :** For Description of Cause, please see DIR filed April 24, 2020 attached to recall 20E-026.**Identification of Any Warning that can Occur :** For Identification of Any Warning that can Occur, please see DIR filed April 24, 2020 attached to recall 20E-026.**Involved Components :**

Component Name : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : DENSO International America, Inc.

Address : 24777 Denso Drive
Southfield Michigan 48086

Country : United States

Chronology :

See attached file "210930_DENSO DIR Amendment 4_20E-085" for full chronology.

Description of Remedy :

Description of Remedy Program : The remedy program, if any, will be determined by vehicle manufacturers.

How Remedy Component Differs from Recalled Component : The impeller of fuel pumps utilized for a remedy component have higher density.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : The recall schedule will be decided by vehicle manufacturers.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : American Honda Motor Co., Inc.
Address : 1919 Torrance Blvd.
Torrance CA 90501-2746
Country : US
Company Phone : NR

Name : Ford Motor Company
Address : 1 American Rd
Dearborn MI 48126
Country : US
Company Phone : 8003923673

Name : Mazda North American Operations
Address : 1025 Connecticut Avenue NW
Washington DC 20036
Country : US
Company Phone : NR

Name : Magnuson Products, LLC
Address : 1990 Knoll Drive, Building A
Ventura CA 93003
Country : US
Company Phone : 8056428833

Name : Subaru of America, Inc.
Address : One Subaru Drive
Camden NJ 08103
Country : US
Company Phone : 8564888500

Name : Toyota Motor North America, Inc.
Address : 6565 Headquarters Drive
Plano TX 75024
Country : US
Company Phone : 4692924000

Name : Mitsubishi Motors North America, Inc.

Address : 4015 Aspen Grove Dr
Franklin TN 37067

Country : US

Company Phone : 8654414166

* NR - Not Reported