

**Manufacturer Name :** DENSO International America, Inc.

**Manufacturer Information :**

Manufacturer Name : DENSO International America, Inc.

Address : 24777 Denso Drive, Southfield, Michigan 48086 U.S.A

Company phone : +1 248 350 7500

This supplements DENSO's Amended Part 573 Report of August 11, 2021 (20E-085) concerning the fuel pump assembly issue on certain Toyota, Honda, and Subaru vehicles.

This recall affects certain vehicles equipped with specific low pressure fuel pumps with an impeller which may become deformed under certain conditions which could render the fuel pump inoperable.

DENSO sells low pressure fuel pumps of similar but not identical design and construction to other vehicle manufacturers. The vehicles of the other vehicle manufacturers possess different fuel delivery systems, engine configurations, and other variables. DENSO is cooperating with other vehicle manufacturers' investigations. Recently Subaru made safety recall notification and implemented a safety recall (21V-587) for certain Subaru vehicles for a particular period. Thus, DENSO is amending its Part 573 Report for this recall (20E-085) to add the Subaru vehicles (population of 165,026) to the affected population.

Number of potentially involved:

Amended to: 2,318,892

Part No. :

Amended to: See attached file "Amendment 2\_Part No list"

Chronology :

Amended to add:

July 2021

Subaru filed a safety recall notice (21V-587) to cover additional Subaru vehicles that were not included in its earlier recall notices.

DENSO sells low pressure fuel pumps of similar but not identical design and construction to other vehicle manufacturers. The vehicles of the other vehicle manufacturers possess different fuel delivery systems, engine configurations, and other variables to those Toyota and Honda and Subaru included in its recall. DENSO is cooperating with other vehicle manufacturers' analysis.

Comments :

Amended to include:

Number of potentially involved: 2,318,892

This is the sum of the vehicle populations announced when Toyota filed safety recall notice 20V-682, Honda filed safety recall notice 21V-215, and Subaru filed safety recall notice 21V-587.