Action Required For Identifying the Recalled Bendix® SL-4™ Stop Light Switch



Bendix[®] SL-4[™] Stop Light Switch

Identifying Bendix[®] SL-4[™] Stop Light Switches Covered in this Field Action

The Bendix[®] SL-4[™] stop light switch includes a date code printed on a white Bendix label affixed to the unit. The date code, featuring a "Month/Year" format, appears in red type. Stop light switches covered by this campaign would have a date code of either 12/19 or 01/20. For example, an SL-4 stop light switch manufactured in December of 2019 will have a date code of "12/19" in red type, and an SL-4 stop light switch manufactured in January of 2020 will have a date code of "01/20" in red type. Verification of the date code is required to determine if the stop light switch is a part of the recall campaign.

If the date code is either 12/19 or 01/20, it can be assumed the stop light switch is part of the recall campaign and needs to be replaced. If the date code is neither 12/19 nor 01/20, it can be assumed the stop light switch is not affected by this recall or the switch has already been replaced.