

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS5295  
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 24, 2020

Subject: N202292780 - Safety Recall  
Front Seat Belt Webbing Sensor

Models: 2019 Chevrolet LCF 3500 equipped with 6.0L V8 (RPO L96)  
2019 Chevrolet LCF 4500 equipped with 6.0L V8 (RPO L96)  
2020 Chevrolet LCF 4500 HD equipped with 5.2L Diesel (RPO I1B)  
2020 Chevrolet LCF 4500 XD equipped with 5.2L Diesel (RPO I1B)  
2020 Chevrolet LCF 5500 HD equipped with 5.2L Diesel (RPO I1B)  
2020 Chevrolet LCF 5500 XD equipped with 5.2L Diesel (RPO I1B)

To: All General Motors Medium Duty Dealers

General Motors is releasing Safety Recall N202292780 today. The total number of U.S. vehicles involved is approximately 47. Please see the attached bulletin for details.

Vehicles involved in this recall were placed on stop delivery January 17, 2020. Once the service procedure contained in the bulletin has been performed on the vehicle, the vehicle is released from stop delivery and the vehicle can be delivered to the customer.

**Question and Answer Document (Q&A)**

Attached to this message you will find a document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

**Customer Letter Mailing**

The customer letter mailing will begin on February 14, 2020.

**Global Warranty Management (GWM)**

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated January 24, 2020. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS