Audi AUDI DEALER COMMUNICATION

## Advance Notice – Safety Recall 20BX / Fuel Tank Heat Shield Bracket

This notice is for:	<ul> <li>✓ Dealer Principal</li> <li>✓ General Manager</li> <li>✓ Sales Managers</li> </ul>		v Pa	rvice Manager      ✓    Wa rts Manager      ✓    Teo rvice Advisor	arranty Administrator chnicians
Date:	February 27, 2020				
lssue:	In a frontal crash, the fuel tank could be damaged by a fuel tank heat shield bracket. Damage to the fuel tank may cause a fuel leak. Leaking fuel, in the presence of an ignition source, may lead to a fire.				
Repair:	<ul> <li>REPAIR NOT YET AVAILABLE</li> <li>Check daily campaign open inventory report or OMD for affected vehicles in inventory</li> <li>Repair every affected inventory vehicle <u>before delivery to consumers</u>.</li> </ul>				
Affected Vehicles	Country	Beginning Model	Ending Model	Vehicle	Vehicle Count
		Year	Year		count
	USA	Year 2016	<b>Year</b> 2019	TT ROADSTER quattro TT COUPE quattro	
	USA CAN				8,572
Notes:	CAN *Counts reflect in Elsa <u>on the v</u> inquiry & verif	2016 2016 et overall populati <u>day of repair</u> to ve fication source.	2019 2019 ion; some vehicl erify that a VIN	TT COUPE quattro TT ROADSTER quattro	8,572 2,139 ck Campaigns/Actions screen lsa is the <u>only</u> valid campaign

## -END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Audi Public Relations.