

CAMPAIGN LAUNCH STATUS

SERVICE ACTIONS AND RECALLS –STATUS UPDATES



SERVICE ACTIONS N451 AND H291 19-20MY AJ20P COOLANT PUMP OPERATION

EFFECTIVE JUNE 10TH 2020 . THESE 2 CAMPAIGNS HAVE BEEN SUSPENDED. (Aftersales Bulletin NAS20.06.006)

IT HAS BEEN DETERMINED THAT THE NEW SOFTWARE IS MISSING CERTAIN PARTS OF THE CALIBRATION WHICH WILL RESULT IN UNSUCCESSFUL DOWNLOADS

VEHICLES MAY CONTINUE TO BE RETAILED PENDING CAMPAIGN RE-ISSUE

VEHICLES WILL NOT FLAG OPEN IN DDW, TOPIx AND BBSS

RE-LAUNCH TIMING

UPDATED PATHFINDER SOFTWARE IS EXPECTED TO BE AVAILABLE BY JULY 10TH, 2020. PLEASE REVIEW SSM'S 74857 (JAGUAR) AND 74756 (LAND ROVER) FOR REPAIR GUIDANCE PRIOR TO CAMPAIGN RE-LAUNCH.

RECALL H283 10MY XF FUEL TANK FLANGE LEAKING

SAFETY RECALL H283 10MY XF WITH 4.2L V8 ENGINE FUEL TANK FLANGE LEAKING

LAUNCH DELAYED BY A FACTORY PRODUCTION SHUTDOWN. LAUNCH IS NOW PLANNED FOR THE WEEK OF JULY 6TH

