



**IMPORTANT SAFETY RECALL 2020030019**  
**This notice applies to your vehicle, VIN: [REDACTED]**  
**Interior Switch Illumination**  
**NHTSA Recall #20V089**

Mercedes-Benz USA, LLC

Christian Treiber  
 Vice President  
 Customer Services

March, 2020



- A remedy is available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealer as soon as possible.
- This repair will be provided free of charge.

Dear Mercedes-Benz Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has decided that certain Model Year ("MY") 2020-2021 CLA-Class (118 platform), GLE-Class (167 platform) and GLS-Class (X167 platform) vehicles fail to conform with the airbag warning label requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 101 "Controls and Displays." Our records indicate that your vehicle is included in the affected population of vehicles.

**What is the CONCERN?**

MBAG has determined that the instrument cluster software might not meet current production specifications. If the driver were to activate the hazard lights while the ignition is switched off, the hazard light switch would continue to flash as intended, but the illumination of the additional switches in the vehicle (e.g. switch bar, overhead control unit, steering wheel, etc.) might be deactivated. If the interior light switches are not illuminated, they may be more difficult to find and operate, increasing the risk of a crash. The functions of the hazard lights and the overhead control unit as well as all switches would not be affected. All interior cabin lighting remains fully functional.

**What will your DEALER DO?**

An authorized Mercedes-Benz dealer will update the instrument cluster software on the affected vehicles. **This service will be provided free of charge.** We are dedicated to always delivering the best customer experience, and respect for your time is a top priority. While the minimum repair time can be less than one hour, your dealer can provide you with a better estimate of the overall time for this service visit. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle which may increase the required working time.

**What should YOU DO?**



To find the most convenient authorized Mercedes-Benz dealer from your smartphone, scan the QR code to the left.

For additional information and to schedule an appointment, please contact your preferred authorized Mercedes-Benz dealer at your earliest convenience. To locate authorized dealers see [www.MBUSA.com/recall](http://www.MBUSA.com/recall). **Please mention you are scheduling an appointment to update the instrument cluster software under Recall Campaign # 2020030019.**

You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

**Information for Owners**

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

A VIN-based recall lookup tool on our MBUSA.com website now offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See [www.mbusa.com/recall](http://www.mbusa.com/recall). Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372).

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to <https://www.safercar.gov>.

We apologize for any inconvenience this situation may cause you.

Sincerely,

Mercedes-Benz USA, LLC  
 A Mercedes-Benz AG Company  
 One Mercedes-Benz Drive  
 Sandy Springs, GA 30328  
 Phone (770) 705-0600

**IMPORTANT**

VIN: [REDACTED]

If for any reason YOU NO LONGER OWN THIS VEHICLE OR have a CHANGE OF ADDRESS, please COMPLETE THE SECTION BELOW, place in the ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX. If possible, provide the name and address of the present owner so that we may contact them.

- EXPORTED
- LEASE, VEHICLE RETURNED
- SCRAPPED
- SOLD
- STOLEN
- OTHER \_\_\_\_\_

NEW OWNER INFORMATION

MY NEW NAME OR ADDRESS IS:

[Grid for Name]

Last Name, First Name

[Grid for Street]

Street

Apt

[Grid for City, State, ZIP]

City

State

ZIP

[Grid for Email Address]

Email Address

[Grid for Phone]

Phone (numbers only)

[Grid for Mobile]

Mobile (numbers only)

\_\_\_\_\_  
Date

\_\_\_\_\_  
Signature

\*\*\*\* PLEASE DO NOT DETACH. RETURN COMPLETE LETTER \*\*\*\*  
DO NOT USE THE ENCLOSED ENVELOPE FOR OTHER CORRESPONDENCE