

Part 573 Safety Recall Report

20V-096

Manufacturer Name : SMC Trailers**Submission Date :** MAR 06, 2020**NHTSA Recall No. :** 20V-096**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : SMC Trailers

Address : 405 Kesco Drive

Bristol IN 46507

Company phone : 966-5598

Population :

Number of potentially involved : 35

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2020 SMC Laramie

Vehicle Type : TRAILERS

Body Style : ALL

Power Train : NR

Descriptive Information : The recall population was determined by comparing the tire data information in the trailer file to that listed on the placard.

The 44 trailers involved in this recall have incorrect PSI listed on the placard.

Production Dates : APR 12, 2018 - FEB 14, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The PSI listed on the placard is incorrect. It is listed on the placard as 110 PSI. The correct PSI is 80.

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : Tires could be over inflated and fail.

Description of the Cause : Incorrect information was entered into the computer program used to create and print the placards.

Identification of Any Warning that can Occur : The tires could be over inflated which could cause tire failure increasing the risk of a crash without prior warning.

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

Our office manager contacted me February 14, 2020 regarding possible incorrect information being in the computer program used to create and print the placards. This was found when she was adding new tire and wheel combinations into the system. I pulled all trailer files, investigated and found there were indeed errors on the copy of the placards on trailers with 16 inch Westlake tires on steel wheels. The placard had incorrect PSI listed at 110 instead of 80 as it should be.

Description of Remedy :

Description of Remedy Program : We will provide new correct placards at no charge to replace each incorrect placard.

How Remedy Component Differs from Recalled Component : The new placard will list the correct PSI of 80 instead of 110. Federal placard, sticker, part number SD-318.

Identify How/When Recall Condition was Corrected in Production : The data has been corrected in the computer system to correctly state and print the proper PSI. All placards after February 14,2020 will have correct PSI listed.

Recall Schedule :

Description of Recall Schedule : we will create notification letters and envelopes and submit to NHTSA for approval and mail upon approval from NHTSA.

Planned Dealer Notification Date : FEB 28, 2020 - MAR 11, 2020

Planned Owner Notification Date : FEB 28, 2020 - MAR 11, 2020

* NR - Not Reported