



Hyundai Motor America
P.O. Box 20839
Fountain Valley, CA 92728-9937

NHTSA Recall Number: 20V-121
Hyundai Recall Number: 189

IMPORTANT SAFETY RECALL

2013 – 2014 Sonata
Fuel Tube

This is an important Safety Recall.

- Please contact your nearest Hyundai dealer to schedule the repair as soon as possible.
- This repair will be performed at **NO CHARGE** to you.
- To locate your nearest Hyundai dealer and schedule your appointment please visit:
www.HyundaiUSA.com/Campaign189

This notice applies to your Hyundai, VIN: XXXXXXXXXXXXXXXXXXXX

Dear <FirstName LastName,>

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Hyundai has decided that a defect which relates to motor vehicle safety exists in certain model year 2013 – 2014 Sonata vehicles produced by Hyundai Motor Manufacturing Alabama (“HMMA”). Our records indicate that your vehicle is affected.

What is the problem?

The fuel feed line connecting the low pressure fuel pump to the direct injection fuel pump in the subject vehicles could develop a small crack over time due to ambient heat in the engine compartment. A damaged fuel line could allow fuel to leak, increasing the risk of an engine compartment fire.

What will Hyundai do?

Your Hyundai dealer will inspect the fuel feed line for damage and/or leakage and replace the fuel tube if necessary, or improve the connection with a heat-protective tape, between the low-pressure fuel tube and fuel pump. This procedure will be performed at **NO CHARGE** to you.

What should you do?

Please contact your nearest Hyundai dealer to schedule the recall repair as soon as possible.

The actual time required to perform the installation will take less than an hour, however your vehicle may be needed longer, therefore we recommend scheduling a service appointment to minimize inconvenience.

If you have other questions


If you require further assistance, you may contact the Hyundai Customer Care Center at 1-855-371-9460. If you believe that the dealer or Hyundai has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <https://www.safercar.gov>.

Thank you for your attention to this important safety matter. We apologize for any inconvenience this may have caused you.

Hyundai Motor America



Hyundai Motor America
 P.O. Box 20839
 Fountain Valley, CA 92728-9937



If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

No longer own this vehicle?

Changes to your name, address, or if you no longer own this vehicle – Update your information and return this form using the postage-paid envelope enclosed.

Reimbursement Notification

If you paid for repairs related to this recall prior to receiving this notification letter, you may submit your reimbursement request electronically or obtain additional information at www.HyundaiUSA.com/Campaign189 or [1-855-371-9460](tel:1-855-371-9460).

Information Change Card VEHICLE IDENTIFICATION NUMBER

Name and address has changed (print new information below)

LAST NAME	FIRST NAME	M.I.
MAILING ADDRESS	STREET	APT. NO.
CITY	STATE	ZIP
E-MAIL ADDRESS		TELEPHONE NUMBER

I no longer own this automobile as of ___/___/___
DATE

- It was:
- SOLD (Print name and address of new owner above, if known).
 - EXPORTED STOLEN
 - DESTROYED I have NEVER owned this Hyundai
 - The Vehicle Identification Number on this card is incorrect.
 The VIN of my Hyundai is _____