



New Safety Recall Advanced Communication – W12

FCA US LLC (FCA US) has announced a safety recall on certain 2018 - 2020 Model Year (JL) Jeep® Wrangler and 2020 (JT) Jeep® Gladiator vehicles equipped with a manual transmission.

REASON FOR THIS SAFETY RECALL

In some circumstances, the clutch pressure plate on the above vehicles may become overheated through friction, which may lead the pressure plate to fracture. A fractured pressure plate may crack or fracture the transmission case, allowing heated debris to contact ignition sources on the vehicle, potentially leading to a vehicle fire. **A vehicle fire can result in occupant injury and injury to persons outside the vehicle, as well as property damage. A fractured pressure plate may also lead to a loss of propulsion, or generation of road debris. Loss of propulsion, can cause a vehicle crash without prior warning.**

WARNING WHICH CAN PRECEDE OR OCCUR

In some circumstances, the operator may smell a burnt clutch odor, or have excessive or abnormal clutch pedal travel prior to the failure.

SERVICE ACTION

The remedy for this condition is currently under development. Dealers will be notified of the launch of this safety recall by way of established communication methods.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations
FCA US LLC