

Recall Quarterly Report**20V-150**

Manufacturer Name : Triumph Motorcycles America, LTD
NHTSA Recall No. / MFR Recall No. : 20V-150 /SRAN574
Recall Subject : Front Brake Hose may be Improperly Routed
Owner Notification Beginning Date : APR 13, 2020
Owner Notification End Date: APR 13, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 09, 2020	2020-2	1,585	194	0	0

This Document Last Updated : JUL 09, 2020

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.