OMB Control No.: 2127-0004

Recall Quarterly Report

20V-150

Manufacturer Name: Triumph Motorcycles America, Ltd.
NHTSA Recall No. / MFR Recall No.: 20V-150 /SRAN574
Recall Subject: Front Brake Hose may be Improperly Routed

Owner Notification Beginning Date: APR 13, 2020

Owner Notification End Date: APR 13, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 19, 2021	2020-4	1,585	438	0	0
2	OCT 09, 2020	2020-3	1,585	332	0	0
1	JUL 09, 2020	2020-2	1,585	194	0	0

This Document Last Updated: JAN 19, 2021

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.