

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: BMW Recall 20V-xxx: Front Seat Belt Buckles
Date: Friday, March 13, 2020 11:54:54 AM

Publish Date: March 13, 2020
From: Technical Service
Expiration Date: March 27, 2020

DCSnet Message
Urgent



Subject: BMW Recall 20V-xxx: Front Seat Belt Buckles







BMW AG is conducting a Voluntary Safety Recall (effective March 13, 2020) on certain Model Year 2020 BMW vehicles that were produced between January 15, 2020 and March 4, 2020. The issue involves the hall sensor within the driver and/or passenger front seat safety belt buckle.

Please review the attached documents for more details.

The bulletin will be updated when additional information becomes available.

Sincerely,
Technical Service

Attachments:

-  [B720320_Recall_Notice\[82026e77\].pdf](#)
-  [B720320\[82026e76\].pdf](#)
-  [B720320_2020-VariousModels-SafetyBeltBuckleSensor-QA-\(13Mar2020\)\[82026e75\].pdf](#)
-  [B720320_Recall_Notice\[82026e77\].pdf](#)
-  [B720320\[82026e76\].pdf](#)
-  [B720320_2020-VariousModels-SafetyBeltBuckleSensor-QA-\(13Mar2020\)\[82026e75\].pdf](#)

Recipients: BMW SAV (Light Trucks), All Offerings, All Regions, All Areas, All Departments, All Personnel
BMW Passenger Cars, CC-All
BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel



SIB 72 03 20

2020-03-13

RECALL 20V-XXX: FRONT SEAT BELT BUCKLES

MODEL

E-Series	Model Description	Production Date
F91	M8 Convertible	February 11, 2020 – March 4, 2020
F92	M8 Coupe	February 11, 2020 – March 2, 2020
F93	M8 Gran Coupe	February 7, 2020 – March 4, 2020
F97	X3 M Sports Activity Vehicle	January 15, 2020 – February 14, 2020
F98	X4 M Sports Activity Coupe	January 15, 2020 – February 14, 2020
G01	X3 Sports Activity Vehicle	January 15, 2020 – February 17, 2020
G02	X4 Sports Activity Coupe	January 15, 2020 – February 17, 2020
G14	8 Series Convertible	February 7, 2020 – March 4, 2020
G15	8 Series Coupe	February 10, 2020 – March 4, 2020
G16	8 Series Gran Coupe	January 29, 2020 – March 4, 2020
G20	3 Series Sedan	January 28, 2020 – February 18, 2020

AFFECTED VEHICLES

Vehicles which require this Recall Campaign to be completed will show it as “Open” when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

SITUATION

BMW AG is conducting a Voluntary Safety Recall (effective March 13, 2020) on certain Model Year 2020 BMW vehicles that were produced between January 15, 2020 and March 4, 2020. The issue involves the hall sensor within the driver and/or passenger front seat safety belt buckle.

Recall notice and Q&A have been attached for further information.

The bulletin will be updated when additional information becomes available.

Supporting Materials

[picture_as_pdf B720320 Recall Notice.pdf](#)

SAFETY RECALL NOTICE

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Recall 20V-xxx: Front Seat Belt Buckles – B72 03 20

BMW AG is conducting a Voluntary Safety Recall (effective March 13, 2020) on certain Model Year 2020 BMW vehicles that were produced between January 15, 2020 and March 4, 2020.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.