

Part 573 Safety Recall Report

20V-187

Manufacturer Name : Altec Industries Inc.**Submission Date :** MAR 30, 2020**NHTSA Recall No. :** 20V-187**Manufacturer Recall No. :** CSN 756**Manufacturer Information :****Population :**

Manufacturer Name : Altec Industries Inc.

Number of potentially involved : 16

Address : 210 Inverness Center Drive
Birmingham AL 35242

Estimated percentage with defect : 60 %

Company phone : 205 991 7733

Vehicle Information :

Vehicle 1 : 2016-2018 Altec AT200A E350 Cutaway

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by a review of production records that identified units build on cutaway vans.

Production Dates : JAN 15, 2016 - MAR 16, 2018

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : Rear tire size and load rating incorrect

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The load rating of the smaller tire size makes overloading the rear axle likely. An overload condition increases the risk of tire overheating and failure, wheel damage or difficulty steering

Description of the Cause : NR

Identification of Any Warning : The operator may feel vibration during roading and experience low tire that can Occur : pressure or abnormal wear in the rear tires.

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Altec changed the OEM tires and wheels on this configuration of the effected Model to a higher load rating tire. Altec received a report of a rollover accident in a E350 cutaway van. Upon further investigation it was determined that vehicle did not have the recommended tire size for the load rating of the vehicle. The investigation determined that Altec does not have sufficient evidence the effected units were updated during production. There was no report of injury.

Description of Remedy :

Description of Remedy Program : Altec will issue CSN 756 to owners of the vehicles. The CSN will require owners to 1) inspect the tires on the vehicle and 2) Altec will replace any that are not of the correct size and load rating.

How Remedy Component Differs from Recalled Component : This unit configuration is no longer in production.

Identify How/When Recall Condition was Corrected in Production : This unit configuration is no longer in production. Current production models utilize dual rear tires.

Recall Schedule :

Description of Recall Schedule : Altec will issue CSN 756 to owners of the vehicles. The CSN will require owners to 1) inspect the tires on the vehicle and 2) Altec will replace any that are not of the correct size and load rating.

Planned Dealer Notification Date : MAY 26, 2020 - MAY 27, 2020

Planned Owner Notification Date : MAY 26, 2020 - MAY 27, 2020

* NR - Not Reported