



August, 2020

**\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \***

According to our records, your 2020 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** 20S18 - TRANSMISSION SHIFTER CABLE LOCKING CLIP

**What is the issue?**

A clip that secures the transmission cable to the transmission may not be seated properly. The driver may experience the following if this condition occurs:

- **Unintended vehicle movement or roll away, if the parking brake is not applied, increasing the risk of a crash or injury.**
- When exiting the vehicle, the ignition key (if equipped) can be removed and may not provide an instrument panel warning message or chime indicating that the transmission is not in Park.
- The transmission gear as displayed in the instrument cluster may be different than indicated by the position of the transmission shift lever.
- No ability to restart the vehicle, unless the transmission gear as displayed in the instrument cluster is Park or Neutral.

These conditions increase the risk of a crash or injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [www.Fordowner.com](http://www.Fordowner.com).

Thank you for your attention to this very important matter.

Augusto de, 2020

**\* \* \* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \* \* \***

Seg nuestros registros, no se realizaron en sur 2020 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 20S18 - CLIP DE BLOQUEO DEL CABLE DE CAMBIO DE LA TRANSMISIÓN

**¿Cuál es el problema?**

Es posible que el clip que fija el cable de la transmisión no esté correctamente asentado. Si esta condición persiste, el conductor podría experimentar lo siguiente:

- **Movimiento o desplazamiento inadvertido del vehículo si el freno de estacionamiento no está accionado, lo cual aumenta el riesgo de sufrir lesiones o un choque.**
- Al salir del vehículo la llave de encendido (si está equipada) se puede quitar y podría no proporcionar un mensaje en el tablero de instrumentos o una campanilla que indique que la transmisión no está en Estacionamiento.
- El engrane de la transmisión que aparece en el tablero de instrumentos podría diferir de lo que indica la posición de la palanca de cambios.
- Imposible volver a arrancar el vehículo, a menos que el engrane de la transmisión, tal como aparece en el tablero de instrumentos, esté en Estacionamiento o Neutral.

Estas condiciones aumentan el riesgo de sufrir un choque o lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [www.Fordowner.com](http://www.Fordowner.com).

Gracias por su atención en este asunto sumamente importante.

1 of 2

00000000000179



P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C


D / 0005 / 000000000000179 / A



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶



▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶