



PETERBILT MOTORS COMPANY
 A **PACCAR** COMPANY
 1700 WOODBROOK STREET
 DENTON, TEXAS 76205-7864
 940-591-4000

IMPORTANT SAFETY RECALL INFORMATION



U.S. Department of
 Transportation

Issued in Accordance
 With Federal Law



PRESORTED
 FIRST-CLASS MAIL
 U.S. POSTAGE PAID
 CLEVELAND, OH
 Permit No. 469



T3 P1
 1487



-20PBC

RECALL NOTICE

Recall Notice: 18PBB or 20PBC

IMPORTANT SAFETY RECALL

Interim Notification

June 4, 2020

Subject: Safety Recall 18PBB / 20PBC - Tractor ABS Lamp Issue
NHTSA Recall numbers - 18V368 / 20V199

This notice applies to your vehicle. Your VIN(s) can be found on the bottom or back of this page.

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that certain Model Year 2008 through 2019 Model 330, 335, 337, 340, 348, 365, 367, 384, 386, 389, 520, 567, 579, and 587 vehicles manufactured from January 10, 2007 through March 01, 2018 fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 121 - Air brake systems and 136 - Electronic Stability Control Systems on Heavy Vehicles.

The Tractor ABS lamp may not illuminate when the vehicle experiences a loss of battery and/or ignition power to the ABS controller. Unknowingly operating a vehicle with an inoperative ABS system could lead to an increased risk of a crash or injury.

If you own multiple vehicles, your vehicles could be on either recall number. Your Peterbilt dealer will advise the applicable recall number for each vehicle after the software update becomes available.

The problem is ...	The Tractor ABS Lamp may not illuminate when vehicle experiences a loss of battery and/or ignition power to the ABS controller.
What your dealer will do ...	Dealers will update the vehicle software when the update becomes available.
What you must do ...	When you are notified the software update is available, contact your Peterbilt Dealer to schedule an appointment for repair.

Peterbilt has initiated a recall to update the vehicle software. **A software update is not yet available** to correct this condition. However, Peterbilt is required to notify customers of the existence of the identified noncompliance. You will be notified by mail when the software becomes available.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St, Denton, TX 76205, Attn: Customer Services Department, phone 940-591-4220.

If you conclude that Peterbilt Motors Company has not enabled you to remedy this noncompliance in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate you advising us of the new owner's name.

We apologize for any inconvenience this preventive procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise.

We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice.

Sincerely,



Michelle Ponsonby
Director of Customer Service
Peterbilt Motors Company

Our records indicate that these vehicles are affected by 18PBB or 20PBC and are owned by [REDACTED]

[REDACTED]