
INCORRECTLY Installed Clip



Warning

Failure to properly install the clip could cause wheel end separation.