

Part 573 Safety Recall Report

20V-225

Manufacturer Name : Altec Industries Inc.**Submission Date :** APR 21, 2020**NHTSA Recall No. :** 20V-225**Manufacturer Recall No. :** CSN 758**Manufacturer Information :****Population :**

Manufacturer Name : Altec Industries Inc.

Number of potentially involved : 92

Address : 210 Inverness Center Drive
Birmingham AL 35242

Estimated percentage with defect : 100 %

Company phone : 205 991 7733

Vehicle Information :

Vehicle 1 : 2017-2020 Altec ST Spray Truck

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by a review of production records that identified spray trucks that were produced.

Production Dates : OCT 02, 2017 - JAN 17, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : Battery fuse holder improperly mounted

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Electrical short circuits can result in a thermal event which can increase the risk of personal injury and/or property damage

Description of the Cause : NR

Identification of Any Warning : Operator and preventive maintenance inspections may detect evidence of that can Occur : shorting or arcing

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

In February, Altec received a report that a customer experienced a blown fuse due to a fuse holder coming into contact to a battery mounting stud. Altec's investigation determined that that the battery fuse holder was not properly mounted. There have been no other reported incidents

Description of Remedy :

Description of Remedy Program : Altec will issue CSN 758 to owners of the vehicles. The CSN will require owners to install a new battery fuse holder kit.

How Remedy Component Differs from Recalled Component : This field remedy is the production remedy

Identify How/When Recall Condition was Corrected in Production : The fuse holder is secured directly to either the body or the battery in current production units.

Recall Schedule :

Description of Recall Schedule : Altec will issue CSN 758 to owners of the vehicles. The CSN will require owners to install a new battery fuse holder kit.

Planned Dealer Notification Date : JUN 16, 2020 - JUN 17, 2020

Planned Owner Notification Date : JUN 16, 2020 - JUN 17, 2020

* NR - Not Reported