

# Recall Quarterly Report

## 20V-226

**Manufacturer Name :** Mercedes-Benz USA, LLC.

**NHTSA Recall No. / MFR Recall No. :** 20V-226 / 2020050009

**Recall Subject :** Rear Seat Wiring Harness May Be Routed Incorrectly

**Owner Notification Beginning Date :** JUN 04, 2020

**Owner Notification End Date:** JUN 04, 2020



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2        | OCT 19, 2020    | 2020-3         | 120               | 76             | 0                 | 0             |
| 1        | JUL 16, 2020    | 2020-2         | 120               | 28             | 0                 | 0             |

This Document Last Updated : OCT 23, 2020

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.