

Recall Quarterly Report**20V-236**

Manufacturer Name : Triumph Motorcycles America, LTD
NHTSA Recall No. / MFR Recall No. : 20V-236 /SRAN 579
Recall Subject : Brake Pads May Corrode/Detach From Backing Plate
Owner Notification Beginning Date : JUN 26, 2020
Owner Notification End Date: JUN 26, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 09, 2020	2020-2	3,691	0	0	0

This Document Last Updated : JUL 09, 2020

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.