IMPORTANT SAFETY RECALL

Audi of America, Inc.



<MONTH YEAR>

<CUSTOMER NAME>
<CUSTOMER ADDRESS>
<CUSTOMER CITY STATE ZIPCODE>

This notice applies to your vehicle: <MODEL YEAR> <BRAND> <CARLINE>, <VIN>

NHTSA: 20V272

Subject: Safety Recall 38C7 - Transmission Oil Pipe

Dear Audi Owner,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Audi has decided that a defect, which relates to motor vehicle safety, exists in certain 2020 model year Audi vehicles. Our records show that you are the owner of a vehicle affected by this action.

What is the issue? The vehicle may I

The vehicle may leak transmission fluid due to a possibly insufficient friction weld connection between the transmission oil pipe and the flange. If a transmission fluid leak occurs while driving, the road may become slippery, which may increase the risk of a crash.

What will we do?

To correct this defect, your authorized Audi dealer will inspect and, if necessary, replace the affected transmission oil pipe. This work will take about two hours to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule.

What should you do?

Please contact your authorized Audi dealer without delay to schedule this recall repair. For your convenience, you can also visit www.audiusa.com and click on the "Find a Dealer" link to locate a dealer near you and schedule this service.

Precautions you should take

A loss of transmission fluid as a result of a poor weld connection may be recognized by oil marks on the ground beneath the vehicle. A warning lamp indicating a fluid loss also comes on once a certain volume of fluid is lost. If this happens, contact your nearest authorized Audi dealer without delay to have your vehicle inspected.

Lease vehicles and address changes

If you are the lessor and registered owner of the vehicle identified in this action, the law requires you to forward this letter immediately via first-class mail to the lessee within ten (10) days of receipt. If you have changed your address or sold the vehicle, please fill out the enclosed prepaid Owner Reply card and mail it to us so we can update our records.

Can we assist you further?

If your authorized Audi dealer fails or is unable to complete this work free of charge within a reasonable time, please contact Audi Customer Experience at 1-800-253-2834 or via our "Contact Us" page at www.audiusa.com.

Audi of America, Inc. 3800 Hamlin Road Auburn Hills, MI 48326 +1 800 253 2834 www.audiusa.com

IMPORTANT SAFETY RECALL



for open Recalls and **Service Campaigns**

Checking your vehicle To check your vehicle's eligibility for repair under this or any other recall/service campaign, please visit the Recall/Service Campaign Lookup tool at www.audiusa.com and enter your Vehicle Identification Number (VIN).

If you still cannot obtain satisfaction, you may file a complaint with: The Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

We apologize for any inconvenience this matter may cause; however we are taking this action to help ensure your safety and continued satisfaction with your vehicle.

Sincerely,

Audi Customer Protection