

June 2, 2020

Mr. Adrian Diaz Assistant Engineering Director Automotive Safety Office Ford Motor Company 330 Town Center Drive Suite 500/5024 Dearborn, MI 48126

Subject: Front Seat Belt Pretensioners May Not Deploy

Dear Mr. Diaz:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: FORD/TRANSIT CONNECT/2016-2017

Mfr's Report Date: May 27, 2020

NHTSA Campaign Number: 20V-305

Components: SEAT BELTS:FRONT SEAT BELTS:PRETENSIONER

Potential Number of Units Affected: 1,616

Problem Description:

Ford Motor Company (Ford) is recalling certain 2016-2017 Transit Connect vehicles. The front driver and/or passenger seat belt pretensioner initiators could contain an improper generant mix ratio that may prevent the seat belt pretensioners from deploying in the event of a crash.

Consequence:

In the event of a crash, the front driver and/or passenger seat belt pretensioners may not deploy, increasing the risk of injury.

Remedy:

Ford will notify owners, and dealers will inspect and replace seat belt assemblies as necessary, free of charge. This recall is expected to begin June 8, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S25.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

1200 New Jersey Avenue SE Washington, DC 20590

NEF-150DM

20V-305



We have received Ford's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be DeMara Magruder who may be reached by phone at (202) 366-8538, or by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division Office of Defects Investigations Enforcement

