

Recall Quarterly Report

20V-329

Manufacturer Name : Mercedes-Benz USA, LLC
NHTSA Recall No. / MFR Recall No. : 20V-329 / 2020090001
Recall Subject : Shock Absorbers May Wear Prematurely
Owner Notification Beginning Date : OCT 20, 2020
Owner Notification End Date: OCT 20, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 13, 2021	2020-4	38	24	0	0

This Document Last Updated : JAN 15, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.