



MAZDA DEALER EMAIL

TO: Mazda Service & Parts Managers

DATE: July 28, 2020

SUBJECT: Limited Parts Ordering Process for Recall 4520F -- MY20 CX-30 AWD Fuel May Leak from Rear of Vehicle – Ordering Repair Parts

On Wednesday, July 29th dealers can use the [Limited Parts Ordering](#) (LPO) page on eMDCS to order the repair parts for Recall 4520F. There will be a daily maximum allotment, which will be displayed on the Limited Parts Ordering screen.

Affected Part Numbers: DGJ8-42-165 (O-ring) & CC43-42-693 (Retainer)

This ordering change ensures that all supply is directed to customer repairs. For additional questions, please don't hesitate to email the Dealer Assistance Group at corpdag@mazdausa.com or call 877-727-6626 – Option 2.

Regards,
Carol Whitlock
Senior Analyst, Quality Campaigns
Parts Operations Division