

**Recall Quarterly Report****20V-350****Manufacturer Name :** Kymco USA**NHTSA Recall No. / MFR Recall No. :** 20V-350 /Like150-2020-Recall**Recall Subject :** ABS Magnetic Sensor Ring May Wear Prematurely**Owner Notification Beginning Date :** JUL 22, 2020**Owner Notification End Date:** JUL 30, 2020

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	MAR 22, 2021	2021-1	1,786	756	0	0
2	DEC 23, 2020	2020-4	1,786	690	0	0
1	SEP 23, 2020	2020-3	1,786	475	62	0

This Document Last Updated : MAR 31, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.