## **Recall Quarterly Report**

20V-393

Manufacturer Name: Hyundai Motor America NHTSA Recall No. / MFR Recall No.: 20V-393 /193 Recall Subject: Accessory Power Outlet May Overheat Owner Notification Beginning Date: SEP 28, 2020

**Owner Notification End Date:** SEP 28, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	AUG 01, 2021	2021-2	272,126	52,473	11,649	37,366
3	MAY 04, 2021	2021-1	272,126	43,545	11,649	37,196
2	JAN 28, 2021	2020-4	272,126	31,715	11,649	37,024
1	JAN 06, 2021	2020-3	272,126	4,350	0	36,507

This Document Last Updated: AUG 12, 2021

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.