



Hyundai Motor America
P.O. Box 20839
Fountain Valley, CA 92728-9937

NHTSA Recall Number: 20V-393
Hyundai Recall Number: 193

IMPORTANT SAFETY RECALL

2012 Accent, 2011 – 2012 Elantra, 2011 – 2012 Sonata Hybrid, 2012 Veloster
Tire Mobility Kit Direct Battery Connection Harness

This is an important Safety Recall.

- Please contact your nearest Hyundai dealer to schedule the repair as soon as possible.
- This repair will be performed at **NO CHARGE** to you.
- To locate your nearest Hyundai dealer and schedule your appointment please visit:
www.HyundaiUSA.com/Campaign193

This notice applies to your Hyundai, VIN: XXXXXXXXXXXXXXXXXXXX

Dear <FirstName LastName,>

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Hyundai has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the VIN shown above. Hyundai is conducting a safety recall in the United States to repair the 12V accessory outlet and Tire Mobility Kit air compressor in certain model year 2012 Hyundai Accent, 2012 Hyundai Veloster, and 2011 – 2012 Hyundai Sonata Hybrid vehicles produced by Hyundai Motor Company (“HMC”), certain model year 2011 – 2012 Hyundai Elantra vehicles produced by Hyundai Motor Company (“HMC”) and Elantra vehicles produced by Hyundai Motor Manufacturing Alabama (“HMMA”).

What is the problem?

The subject vehicles are equipped with accessory Tire Mobility Kits (“TMK”) intended for use by customers to temporarily repair a flat or punctured tire. The TMK air compressor can be powered by the vehicle’s 12V accessory outlet, which contains a thermal fuse that cuts the outlet’s power to safeguard against overheating. Certain accessory outlets may have been excessively tightened when they were installed, disabling the operation of the thermal fuse. If the thermal fuse is disabled, the outlet could eventually overheat with prolonged use of the TMK air compressor. An overheated accessory outlet increases the risk of fire.

What will Hyundai do?

Your Hyundai dealer will install the Direct Battery Connection Harness to the TMK air compressor. This procedure will be performed at **NO CHARGE** to you.

What should you do?

Please contact your nearest Hyundai dealer to schedule the recall repair as soon as possible.

The actual time required to perform the repair will take less than one hour, however your vehicle may be needed longer. Therefore, we recommend scheduling a service appointment to minimize inconvenience.

If you have other questions


If you require further assistance, you may contact the Hyundai Customer Care Center at 1-855-371-9460. If you believe that the dealer or Hyundai has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <https://www.safercar.gov>.

Thank you for your attention to this important safety matter. We apologize for any inconvenience this may have caused you.

Hyundai Motor America



Hyundai Motor America
 P.O. Box 20839
 Fountain Valley, CA 92728-9937



If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

No longer own this vehicle?

Changes to your name, address, or if you no longer own this vehicle – Update your information and return this form using the postage-paid envelope enclosed.

Reimbursement Notification

If you paid for repairs related to this recall prior to receiving this notification letter, you may submit your reimbursement request electronically or obtain additional information at www.HyundaiUSA.com/Campaign193 or [1-855-371-9460](tel:1-855-371-9460).

Information Change Card VEHICLE IDENTIFICATION NUMBER

Name and address has changed (print new information below)

LAST NAME	FIRST NAME	M.I.
MAILING ADDRESS	STREET	APT. NO.
CITY	STATE	ZIP
E-MAIL ADDRESS		TELEPHONE NUMBER

I no longer own this automobile as of ___/___/___
DATE

It was:

- SOLD (Print name and address of new owner above, if known).
- EXPORTED STOLEN
- DESTROYED I have NEVER owned this Hyundai

The Vehicle Identification Number on this card is incorrect.
 The VIN of my Hyundai is
