

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS5466
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 31, 2020

Subject: N202305381-01 - Safety Recall
Reduced (RH) Roof Rail Air Bag Performance
Revised service procedure regarding airbag disposal.

Models: 2020 Buick Enclave
2020 Cadillac XT5
2020 Cadillac XT6
2020 Chevrolet Blazer
2020 Chevrolet Silverado
2020 Chevrolet Traverse
2020 GMC Acadia
2020 GMC Sierra

To: All General Motors Dealers:

The service procedure in this bulletin has been revised to instruct technicians to NOT deploy roof rail airbag(s) after removal.

Do not deploy or dispose of removed roof rail airbag(s) until you receive revised disposal/deployment instructions. Airbag components could separate from the module during deployment and cause serious injury. Do not use the airbag deployment instructions in Service Information (SI). Removed airbags should be stored or quarantined in a safe location until revised roof rail airbag deployment instructions are provided.”

Please discard all previous copies of bulletin N202305381.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS