Recall Quarterly Report

20V-457

Manufacturer Name : Nova Bus (US) Inc. NHTSA Recall No. / MFR Recall No. : 20V-457 /CR4943 Recall Subject : Loss of Drive from Fractured Pressure Switch Owner Notification Beginning Date : SEP 15, 2020 Owner Notification End Date: SEP 15, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	OCT 21, 2021	2021-3	34	17	0	0
4	JUL 23, 2021	2021-2	34	0	0	0
3	APR 29, 2021	2021-1	34	0	0	0
2	JAN 08, 2021	2020-4	34	0	0	0
1	OCT 30, 2020	2020-3	34	0	0	0

This Document Last Updated : OCT 28, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7