

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS5475
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 7, 2020

Subject: N202309350 - Noncompliance Recall
Interior Trunk Release Button Inoperative Ten Minutes After Power Off

Models: 2020 Chevrolet Corvette

To: Select General Motors Dealers

General Motors released Noncompliance Recall N202309350 on August 6, 2020. Attached are the inventory vehicles associated with this recall that remain in "open" status in Investigate Vehicle History (IVH). Any vehicles that were successfully programmed via over the air programming (OTA) and in "closed" status in IVH are not included in this stock VIN list.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen has been updated as of August 7, 2020.

Dealers can and should perform this non-compliance bulletin on any vehicle with an "open" status in IVH. Due to the fact that vehicles will continue to be closed in IVH following successful OTA programming, dealers should always check the status in IVH before performing any vehicle repairs.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS