

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS5494
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 3, 2020

Subject: N202309350-01 - Noncompliance Recall
Interior Trunk Release Button Inoperative Ten Minutes After Power Off
Service Procedure Updated and Customer Letter Added

Models: 2020 Chevrolet Corvette

To: All General Motors Dealers

Bulletin N202309350-01 has been revised to update the service procedure and to include a copy of the customer notification letter. Please discard all copies of bulletin N202309350.

Customer Letter Mailing

The customer letter mailing will begin today, September 3, 2020.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS