## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

20V-462

**Manufacturer Name:** New Flyer of America, Inc.

NHTSA Recall No. / MFR Recall No.: 20V-462 /R20-007 Recall Subject: Loss of Drive from Fractured Pressure Switch

**Owner Notification Beginning Date :** AUG 17, 2020

**Owner Notification End Date:** AUG 19, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	APR 23, 2021	2021-1	152	135	0	0
2	JAN 22, 2021	2020-4	152	124	0	0
1	OCT 29, 2020	2020-3	152	88	0	0

This Document Last Updated: APR 28, 2021

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.