

**Recall Quarterly Report****20V-462****Manufacturer Name :** New Flyer of America, Inc.**NHTSA Recall No. / MFR Recall No. :** 20V-462 /R20-007**Recall Subject :** Loss of Drive from Fractured Pressure Switch**Owner Notification Beginning Date :** AUG 17, 2020**Owner Notification End Date:** AUG 19, 2020

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 22, 2021	2020-4	152	124	0	0
1	OCT 29, 2020	2020-3	152	88	0	0

This Document Last Updated : JAN 25, 2021

**Definitions :**Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.