

**Recall Quarterly Report****20V-462**

**Manufacturer Name :** New Flyer of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 20V-462 /R20-007  
**Recall Subject :** Loss of Drive from Fractured Pressure Switch  
**Owner Notification Beginning Date :** AUG 17, 2020  
**Owner Notification End Date:** AUG 19, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	OCT 28, 2021	2021-3	152	134	0	0
4	JUL 30, 2021	2021-2	152	142	0	0
3	APR 23, 2021	2021-1	152	135	0	0
2	JAN 22, 2021	2020-4	152	124	0	0
1	OCT 29, 2020	2020-3	152	88	0	0

This Document Last Updated : OCT 29, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.