

**Recall Quarterly Report****20V-472**

**Manufacturer Name :** Triumph Motorcycles America, Ltd.  
**NHTSA Recall No. / MFR Recall No. :** 20V-472 /SRAN 584  
**Recall Subject :** Misrouted Wiring Harness May Become Damaged  
**Owner Notification Beginning Date :** AUG 28, 2020  
**Owner Notification End Date:** AUG 28, 2020



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 4        | JUL 09, 2021    | 2021-2         | 2,224             | 1,404          | 0                 | 0             |
| 3        | APR 13, 2021    | 2021-1         | 2,224             | 1,301          | 0                 | 0             |
| 2        | JAN 19, 2021    | 2020-4         | 2,224             | 1,142          | 0                 | 0             |
| 1        | OCT 09, 2020    | 2020-3         | 2,224             | 591            | 0                 | 0             |

This Document Last Updated : JUL 09, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.