

**Recall Quarterly Report****20V-472**

**Manufacturer Name :** Triumph Motorcycles America, LTD  
**NHTSA Recall No. / MFR Recall No. :** 20V-472 /SRAN 584  
**Recall Subject :** Misrouted Wiring Harness May Become Damaged  
**Owner Notification Beginning Date :** AUG 28, 2020  
**Owner Notification End Date:** AUG 28, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	OCT 09, 2020	2020-3	2,224	591	0	0

This Document Last Updated : OCT 09, 2020

**Definitions :**

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.