



**IMPORTANT SAFETY RECALL**

This notice applies to your vehicle(s) with the VIN(s) indicated on the enclosed owner response cards.

**AUTOCAR, LLC SAFETY RECALL ACX-2005  
NHTSA RECALL NO. 20V496**

**April 2021**

**Dear Autocar Truck Owner:**

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect which relates to motor vehicle safety exists in 78, 2019 model year Xpeditor chassis. These chassis were manufactured between August 20, 2018 and March 13, 2019 with non-sequential serial numbers in the range of 228812 through 230040. Our records indicate that your vehicle was manufactured within this time period and may contain the defect described herein.

**MODELS AFFECTED:** Autocar Xpeditor MY 2019

**COMPONENTS AFFECTED:** A potential stall/hesitation during launch when operated from the right-side stand-up position with the hydraulic system engaged.

**SAFETY DEFECTS AND POTENTIAL RISKS:** When operated from the right-side stand-up position with the hydraulic system engaged, the vehicle could experience a stall/hesitation during launch. If this occurs while operating on an incline, the vehicle could move rearward, increasing the risk of a crash, personal injury or property damage.

**REPAIR REQUIRED:** A hill start aid system will be installed at no charge.

**TIME REQUIRED FOR THE REPAIR:** The estimated labor time to repair your vehicle is 3 hours.

**WHAT YOU SHOULD DO:** To have your vehicle repaired, contact your local authorized Autocar service site or email [warranty@autocartruck.com](mailto:warranty@autocartruck.com).



**PRIOR REPAIRS:** If you have previously paid for repairs relating to this recall you may be entitled to recover the amount you paid for those repairs. Submit a copy of all documentation supporting your claim to Autocar at the address set forth below in the "Assistance" section.

**NOTICE REGARDING LEASED VEHICLES:** If you are a Lessor (as defined below) of a vehicle that is affected by this notice, you are obligated under federal law to provide a copy of this Notice to the lessee of such vehicle within 10 days of your receipt of this Notice. Further, you must maintain a record, which identifies the lessee(s) to whom you send a copy of this Notice, the date you send the Notice and the VIN of the vehicle that you have leased to the lessee(s).

For purposes of this Notice, the term "Lessor" means a person or entity that is the owner, as reflected on the vehicle's title, of any five or more leased vehicles, as of the date of this Notice.

**OWNER RECALL RESPONSE CARD:** The enclosed Owner Recall Response Card identifies your vehicle. Please complete this postage-paid card and return it to Autocar. If you do not own, have sold or have traded the vehicle identified on the card, please indicate that on the postage-paid card and return it to Autocar.

**ASSISTANCE:** If you need assistance with this recall, call our toll-free numbers below or write to Autocar at:

**CE:**  
Autocar, LLC  
Service & Warranty Departments  
551 S. Washington St.  
Hagerstown, Indiana 47346  
888-218-3611 (Toll Free)  
877-973-3486 (Toll Free)

You may also submit a complaint to:

Administrator  
National Highway Traffic Safety Administration  
1200 New Jersey Avenue SE  
Washington, DC 20590

or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this recall may cause, but we hope you recognize Autocar's concern for your safety and satisfaction with your vehicle.

Sincerely,

**AUTOCAR, LLC**

ACF 00002 Rev. 000