



KEYSTONE
RV COMPANY

RECREATIONAL VEHICLE
SAFETY RECALL NOTICE

Safety Recall: 20V-538
Transport Canada: 2020-422
Safety Advisory: 20-385
October 2, 2020

Recall Population

2021 Fuzion Models: 357, 369, 373, 379, 419, 424, 427, 429, 430
2021 Impact Models: 343, 359, 367, 415

Serial Number Ranges:

2021 Fuzion MF810184 - MF810279

2021 Impact MF815054 - MF815077

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for
this recall***

It has been decided that the vehicles in the recall population may have an auxiliary fuel supply tank that may have been manufactured with improper grade 2 bolts rather than proper grade 5 bolts for the tank mounting straps. Under certain conditions during travel, the grade 2 bolts may break at the mounting point allowing the auxiliary fuel supply tank to become detached from the frame of the unit leading to an increased risk of vehicle crash and/or fire.

***What we
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to inspect the tank strap mounting bolts and replace if found to be a grade 2 bolt with a grade 5 bolt. The service and parts required for this corrective action will be provided at no charge to you.

***What we
need you to
do***

Do not fill the tanks to capacity with fuel. Transport the unit to the nearest authorized dealer with empty tanks for repairs to be completed. As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 1 hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)



PO Box 2000 – Goshen, IN 46527-2000
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com