

Recall Quarterly Report

20V-543

Manufacturer Name : Hyundai Motor America
NHTSA Recall No. / MFR Recall No. : 20V-543 / 195
Recall Subject : ABS Unit may cause Engine Compartment Fire
Owner Notification Beginning Date : NOV 02, 2020
Owner Notification End Date: NOV 02, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 28, 2021	2020-4	652,024	56,223	2,937	6,816

This Document Last Updated : FEB 02, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.